Trimble Advanced Positioning

ALLOY AND NETR9 REFERENCE RECEIVERS 5.42 FIRMWARE RELEASE

These release notes describe the latest improvements made to the Trimble® Alloy™ and NetR9™ reference receivers.

- Introduction
- Alloy and NetR9 common features and changes
- Alloy-only features and changes
- Feature comparison table
- Upgrade procedure
- Legal notices

Introduction

These release notes describe version 5.42 firmware improvements for the Alloy and NetR9 reference receivers. All Alloy receivers are entitled to firmware version 5.42. The NetR9 receiver must have minimum firmware date of 1 November 2018, or a more recent date to use firmware version 5.42. If necessary, contact your Trimble dealer to purchase an NetR9 extended warranty. Before you perform a firmware upgrade, ensure that you download and back up any files or configuration settings.

Note – While many improvements listed are available on both Alloy and NetR9 receivers, some improvements are only available on the Alloy receiver. The Alloy receiver has new powerful hardware architecture that can support new capabilities. The supported features depend on the receiver model and options installed.


Version: 5.42 Date: August 2019



Alloy and NetR9 common features and changes

Tracking and data formats

- Activated Galileo message 1045 for broadcast ephemeris in RTCM.
- Modified the receiver's ability to handle QZSS LEX L6 data when using the RT27 format.
- Improved the performance and reliability of QZSS L1C tracking by fixing issues seen in previous firmware versions where the receiver occasionally could not track QZSS L1C.
- Introducing RINEX 3.04 support RINEX 3.04 includes the following:
 GLONASS CDMA (Code Division Multiple Access) signals, BeiDou Generation III satellites, and QZSS II signals. In addition to the new signals, the RINEX 3.04 text has been edited to improve the description of messages, fields, and overall readability.




• Revised GLONASS navigation time frame changes in RINEX 3.03 and 3.04 - UTC time of week instead UTC time of the day for GLONASS ephemeris.

Improvements

- CPU utilization to significantly improve the stability and reliability of the receiver.
- Added and updated the antenna configuration list to include new third-party antennas.
- New Secure socket layer (SSL) security enhancements and functionality. Firmware version
 5.42 consists of the following SSL features:
 - Authenticate NTRIP caster This gives the receiver the ability to load a remote NTRIP Caster's certificates for authentication.

• Send Client certificate – Load a CLIENT certificate into the receiver.



Alloy-only features and changes

Tracking and data formats

GPS Block IIIA L1C

The Alloy receiver now supports the new GPS Block IIIA L1C signal. Please note that GPS III satellites are still launching and are not fully operational. The L1C signal frequency is 1575.42 MHz, and the Alloy receiver requires a new option code to track the L1C signal. To obtain an upgrade code for the L1C signal, please contact Trimble Support (RTNS_Support@trimble.com) with the serial numbers of your Alloy receivers.

Frequency	GPS Block I , II, and their variations	GPS Block IIIA	Receiver
L1-C/A	х	х	NetR9 / Alloy
L2E	х	x	NetR9 / Alloy
L2C	х	х	NetR9 / Alloy
L5	х	х	NetR9 / Alloy
L1C		x	Alloy

Note – The NetR9 receiver cannot track GPS Block IIIA L1C signals.


Alloy with version firmware 5.42, has continued to improve its BeiDou and Beidou generation III support. Below is a list of new BeiDou features and enhancements

- Improved BeiDou Multipath mitigation with EVEREST™ Plus
- Extended the Beidou almanac for the B1I signal.
- Updated BeiDou PRN range to 63

GP	GLO	NASS	Galile	eo BeiD)ou	QZ	SS	IRNSS	SBAS
sv	Enable	lgnore Health	sv	Enable	lgno Hea		sv	Enable	lgnore Health
1		\square	22		⊵]	43		\square
2		\square	23	\square	⊵]	44		\square
3		\square	24		⊵]	45	\checkmark	\square
4	\square	\square	25	\square	⊵]	46		\square
5		\square	26		⊵]	47		\square
6			27	\square	⊵]	48		\square
7	\checkmark		28		⊵]	49		\square
8		\square	29		⊵]	50		
9		\square	30		⊵]	51		\square
10		\square	31		⊵]	52		
11	\checkmark	\square	32		₽]	53	abla	
12	\checkmark	\square	33		⊵]	54		
13		\square	34		⊵]	55		
14		\square	35	\square	⊵]	56	\square	
15		\square	36		⊵]	57	abla	\square
16	\checkmark	\square	37		⊵]	58		
17		\square	38	\square	⊵]	59	\square	\square
18		\square	39	\square	⊵]	60	\square	\square
19		\square	40	\square	⊵]	61	\square	\square
20		\square	41	\square	⊵]	62	\square	\square
21		\square	42	\square	⊵]	63		\square
Enable All Ignore Health All Disable All OK Cancel									

Improvements

- Upgraded anti-spoofing detection in the Alloy Receiver.
- Added the Internal Battery UPS option for the Alloy receiver (the NetR9 receiver already has this feature).



Feature comparison table

Tracking and data formats	Alloy	NetR9	
GPS Block IIIA L1C support	Υ	N	
Galileo message 1045 RTCM	Υ	Υ	
QZSS Lex L6 RT27	Υ	Υ	
RINEX 3.04 support	Υ	Υ	
RINEX improvements	Υ	Υ	
BeiDou Gen 3 extended tracking	Υ	N	
BeiDou multipath improvements	Υ	N	
Improvements			
CPU load enhancements	Υ	Υ	
New SSL features	Υ	Υ	
Anti-spoofing improvements	Υ	N	
Web Interface			
Third-party antenna support	Υ	Υ	
UPS Battery option	Υ	Υ	

Upgrade procedure

Before upgrading the firmware, please back up and save the receiver's configuration.

For the NetR9 receiver, ensure that the receiver firmware warranty date is 1 November 2018 or later. The Alloy receiver has lifetime firmware upgrades.

To upgrade, use one of the following methods:

- If using the WinFlash utility: Use the latest version that is available with the version 5.42 Web package.
- Receiver Web Interface: Download and install the version 5.42 *.TIMG file.

Legal notices

Trimble Inc.
Engineering & Construction Group
10368 Westmoor Drive
5475 Kellenburger Road
Dayton, Ohio 45424-1099
USA

800-538-7800 (toll free in USA) +1-937-245-5600 Phone +1-937-233-9004 Fax www.trimble.com

Copyright and trademarks

© 2019, Trimble Inc. All rights reserved.

Trimble, and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries. Alloy, EVEREST, and NetR9 are trademarks of Trimble Inc. Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. All other trademarks are the property of their respective owners.

Release notice

This is the August 2019 release (Revision A) of the Release Notes. It applies to version 5.42 of the Alloy and NetR9 firmware.

Product warranty information

For applicable product warranty information, please refer to the Warranty Card included with this Trimble product, or consult your Trimble reseller.