



Trimble Infrastructure

GNSS SERIES RECEIVERS

These release notes describe the latest improvements made to the Trimble® NetR9™ GNSS Infrastructure series receivers.

- ▶ Introduction
- ▶ New Features and Changes
- ▶ Upgrade Procedure
- ▶ Legal Notices

Introduction

These release notes describe the improvements made to the Trimble NetR9 Infrastructure series receivers.

With this release, these products can now use version 5.15 firmware.

Note – *Not all receivers support all features contained within this firmware release. The supported features will depend on the receiver model and options installed.*

To load and use firmware version 5.15, you must have a valid firmware warranty, dated 1 May 2015 or later. If necessary, contact your Trimble dealer to purchase a warranty.

Before you perform a firmware upgrade, download and back up any files or configuration settings.

New Features and Changes

General

- ▶ Updated antenna library database.

Data logging

- ▶ The ability to select and download multiple T02 files simultaneously has been added.

Tracking

- ▶ General GNSS constellation updates.
- ▶ Improved leap second handling in certain cases where GPS tracking is not available.

Web interface and front panel

- ▶ Improved web page rendering in the Internet Explorer® internet browser.

Version 5.15
Revision A
December 2016

Upgrade Procedure

Make sure that the receiver firmware warranty date is 1 May 2015 or later.

To upgrade, use one of the following methods:

- ▶ WinFlash utility: Use the latest version that is available with the version 5.15 Web package.
- ▶ Receiver Web User Interface: Download and install the version 5.15 *.TIMG file.

Legal Notices

Trimble Inc.
Engineering and Construction Group
5475 Kellenburger Road
Dayton, Ohio 45424-1099
USA

800-538-7800 (toll free in USA)
+1-937-245-5600 Phone
+1-937-233-9004 Fax
www.trimble.com

Copyright and trademarks

© 2007–2016, Trimble Inc. Trimble and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries. NetR9 is a trademark of Trimble Inc. Developed under a License of the European Union and the European Space Agency. Microsoft and Internet Explorer are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. All other trademarks are the property of their respective owners.

Release notice

This is the December 2016 release (Revision A) of the *Infrastructure GNSS Receivers Release Notes*. It applies to version 5.15 of the receiver firmware.

Product warranty information

For applicable product warranty information, please refer to the Warranty Card included with this Trimble product, or consult your Trimble reseller.

Notice to our European Union customers

For product recycling instructions and more information, please go to www.trimble.com/ev.shtml.

Recycling in Europe: To recycle Trimble WEEE (Waste Electrical and Electronic Equipment, products that run on Electric power), call +31 497 53 24 30 and ask for the "WEEE Associate".

Or, mail a request for recycling instructions to:

Trimble Europe BV
c/o Menlo Worldwide Logistics
Meerheide 45
5521 DZ Eersel, NL.

